



SERVICE BULLETIN

Date: 9/18/2002

Number: SB0209

Subject: New Design Prowlers (52K23A, 52K25A, 52K27L, 61K25A, 61K27L, 61B27LD, 61B31LP, 72K27L, 72B27LD, 72B31LP)

Details:

New design Prowlers with fuel tank/fender, part #'s 593001 and 593002, need to have a caution fuel label, part # 823318, added to the metal plate beside the fuel tank/fender. Please contact Encore for the caution label, part # 823318. Encore will allow 15 minutes, labor code 247, to apply the label under warranty.

Thank you,
Encore Service Department
Billy Harms
Roy Neemann
Dana Haecker