

SERVICE BULLETIN

Date: 8/5/2005

Number: SB0502


Subject: Hydro Lines on 52K23X

Details: Concerning the 52K23X, the two lower steel hydraulic lines have been changed to rubber lines on units with serial # 51622 and above. The two steel lines that are being replaced are:

533015 RH Outside Line (item #16 below)

533012 LH Inside Line (item #14 below)

The new replacement rubber hydraulic line is part # **533113**. Below is a diagram indicating the two steel lines now being replaced by the 533113 rubber hydraulic line.



5330015 - RH OUTSIDE LINE *

533012 - LH INSIDE LINE *

* Now being replaced by the 533113 - Rubber Hydraulic Line

Also note that the Encore part # for the Parker **Hydro Pump** is **533079** and the Encore part # for the Parker **Wheelmotor** is **583325** on the Encore X-treme 52K23X.

Please insert this sheet into the "Hydro Components" section of your X52 Illustrated Parts Manual for future reference.