




SERVICE BULLETIN

Date: 8/24/2005

Number: SB0505

Subject: Deck Tensioner on 52K23X

Details: Encore 52K23X units with serial # 51622 and above now have a different tensioner pulley installed on the deck assembly. Please make note of the new tensioner assembly and part # changes as shown in the diagram below.



Please make note of these new parts and part numbers in your 52K23X illustrated parts manual.