



# SERVICE BULLETIN

**Date:** 2/28/1994

**Number:** SB9401-17

**Subject:** Threaded Link on Speed Control Assy for Hydro Walk-Behind units

---

---

**Details:**

The threaded link, part # 453005 (item # 79), will no longer be available for service. It will be replaced by part # 453137 - adjuster link. You will also have to change the quantity to one on part numbers:

<u>Part #</u>	<u>Description</u>
104750	1/4-28 Jam Nut (item # 56)
453070	1/4" Rod End (item # 78)

You must then add one of each of the following to the parts list:

<u>Part #</u>	<u>Description</u>
103018	1/4-28 LH Jam Nut
453135	.25 Rod End - LH Thread

The purpose of this is to simplify the adjustment of the speed control in the set-up operation.

Please make these changes in your parts manuals.

A service kit includes the following parts:

<u>Part #</u>	<u>Description</u>
453137	Adjuster Link
103018	1/4 Jam Nut
453135	.25 Rod End

This kit will be available for replacement on older units as normal wear occurs.

Thank you,  
Encore Service Department