

SERVICE BULLETIN

Date: 5/4/1995 **Number:** SB9504-1

Subject: Recommended operating speed for Power-Comb

Details:

The Power-Comb shaft is not designed to operate at high engine rpm's. Thus, it is best to set the engine speed at half-throttle.

IMPORTANT! Failure to throttle back the engine, as recommended, may result in premature fatigue of the spring-tine.

CAUTION! Setting the comb tines in too low of position may cause damage to grass also causing premature failure of the comb tines.

The purpose of this bulletin is to make users aware of the recommended operating speed of the Power-Comb.

Thank you, Encore Service Department

Encore Part Number: 943089

Rev. A