



# SERVICE BULLETIN

**Date:**

**Number:** SB9508-16A

**Subject:** Bearing, part # 363146

---

---

**Details:**

There has been a run of bearings that have not been properly lubricated from our vendor. When installing new bearings or servicing a new machine, grease cutter-housing to purge bearings taking care not to force out the seal of the bearing. This will help to prevent premature brg. failures.

CONTINUE THIS PRACTICE UNTIL FURTHER NOTICE!!

Thank you,  
Encore Service Department