



SERVICE NOTICE

Date:2/23/09

Number: SN0902

Subject: Prowler Midcut Replacement Hoses

To all Encore Distributors and Servicing Dealers

Units affected are:

61K25A, 61K28A, 61K27L AND 6133A

Details: When ordering pump to wheel motor hoses on 61" Prowler Midcut Models below serial # 54923 you must now order the following items.

Items are:

Qty: 4- **593287** (one required for each hose being replaced.)

Qty: 1- **593285** RH outside line. Replaces 583397

Qty: 1- **593283** RH inside line. Replaces 583396

Qty: 1- **593284** LH inside line. Replaces 583398

Qty: 1- **593286** LH outside line. Replaces 583399

Please make these changes to your Prowler Parts manuals.

Encore Service Department