



SERVICE NOTICE

Date: 7/25/2007

Number: SN0207

Subject: Part # 583385 Pump Belt on Prowler Units with the 27hp liquid cooled Kawasaki Engine

Details: In a continuing effort to improve belt life we have changed the style of the Pump Belt to a **cogged** style belt.

Please advise your Dealer and Customers with the 27hp Liquid Cooled Kawasaki Prowler to inspect the Pump Belt every 300 hours for pre-mature wear or cracking, doing this could prevent damage potential damage to the radiator.

Reminder:

General maintenance of equipment such as keeping equipment clean, checking belt tension, sharp blades and proper engine maintenance will not only extend the life of your equipment but will prevent costly down time.

Encore Service Department.