



SERVICE BULLETIN

Date: 2/13/2002

Number: SB0208

Subject: All Z34 Riders

! SAFETY ALERT!

Details: Fuel line running from the gas tank to the engine.

Please inspect all units for the possibility of the fuel line coming into contact with the cooling fan on the transmission. This can be remedied by simply shortening the fuel line from the gas tank to a length of 23 inches.

**PLEASE NOTIFY ALL DEALERS AND OWNERS OF THE ENCORE Z34
ABOUT THIS POTENTIAL FUEL LINE PROBLEM!**

Thank you,
Encore Service Department
Billy Harms
Roy Neemann
Dana Haecker