




SERVICE BULLETIN

Date: 12/15/2006

Number: SB0306

Subject: Part # 533113 Hose (X-treme) is no longer available

Details: When replacing Part # 533113 Hose you will need to order Part # 533090 Inside Line (length 22.5") and Part # 533089 Outside Line (length 20.81"). Please make this change in your X-treme Parts Manuals.



Subject: Part # 423272 X-treme Pump Belt

Details: When replacing the Pump Belt on X-treme units you must now use Part # 533088 Pump Belt. Please make this change in your X-treme Parts Manuals Only.