

SERVICE BULLETIN


Date: 10/11/2003

Number: SB0307

Subject: Hydro Oil Filter and Clutch Cable Assembly

Details:

Hydro oil filter, part # 423063, is **no longer available** for service or production. It has been replaced by part # 423361. When ordering hydro oil filters for any Walk-Behind Hydro, Z-Series Rider, Prowler Midcut, or Prowler Frontcut, please use part # 423361 when submitting purchase order.



Details:

Clutch cable assembly, part # 253132, which is used on the PL600B (the Encore Power Plugger) is **no longer available** through Encore Mfg. This component may be purchased directly from the Power Plugger manufacturer - Rock Solid. Rock Solid is located in Lincoln, NE and may be contacted at 888-418-9065 or 402-474-6912.

The clutch cable assembly, part # 253132, is shown in the diagram below as item # 23.

