



SERVICE BULLETIN

Date: 7/26/1995

Number: SB9507-26

Subject: Kawasaki's engine overheating to antifreeze level and mixture of water/antifreeze

Details:

When servicing the engine, the mixture should be 50/50 of antifreeze and water. Also, the radiator should be checked daily for fluid level and debris blocking airflow.

When adding fluid to radiator, avoid adding straight 100% antifreeze.

Thank you,
Encore Service Department