



SERVICE BULLETIN

Date:

Number: SB9701

Subject: 25C150 Encore Power Comb

Details:

In a continuing effort to improve Encore product, we have found that by adding a 1/4" Lockwasher to each side of the rubber tine increases the life of the rubber tine mount.

Please add part # 's 105004 - heavy lockwasher for a quantity of 48 pieces.

When re-assembling worn tines, please add one lockwasher to each side of the rubber tine. By doing this allows the tine extra room for flexing at the base of the tine to provide extended life.

Please note that the engine speed must not exceed 3/4 throttle!

Caution: Setting the tines too low to the ground may cause pre-mature failure.

Please make note of these changes to your Parts Manuals.

Thank you,
Encore Service Department