



SERVICE BULLETIN

Date: 12/9/1997

Number: SB9704

Subject: All Encore Z Riders

Details:

In a continuing effort to improve Encore product, we have changed the deck tensioner idler part # 423072. When ordering a replacement idler, you will need to order part # 373068 - Engagement Idler and you will also need to add part # 483017 - RH Idler Spacer.

Please add these items to your Parts Manuals.

Thank you,
Encore Service Department