

SERVICE BULLETIN



WORLDLAWN POWER EQUIPMENT, INC. 2415 Ashland Ave Beatrice, NE 68310 (402) 228-4255 Bulletin Number: SB2001 Date: 3/6/2020

Models Affected:	ENCORE ARROW EA46XS22KW EA50XL24KW EA60XL24KW
Serial Range	201712P5001474 - 201812P5002576
Discrepancy:	Fuel filter is positioned close to the under side of the seat assembly.
Solution:	Relocate fuel filter. See attached instruction sheets
Parts Required:	None
Warranty:	Warranty will reimburse \$20.00 per unit for relocating the fuel filter. Multiple units can be filed on one claim. List additional serial numbers in the notes section of the claim form.