



# SERVICE BULLETIN

Date: 12/15/2006

Number: SB0602

Subject: Part # 422022 Blade Spindle is no longer available.

**Details:** When replacing Part # 422022 Blade Spindle you will need to order Part # 583106 plus the Blade Spindle Pulley (depending on the deck size) and the associated parts such as the Hex nut, Lock washer, Flat washer and Pulley Spacer. You are not required to replace all the Blade Spindles when changing over one.

