



SERVICE BULLETIN



Bulletin Number: SB1104

Date: 8/18/2011

Subject: Addendum to X-Treme 48", 52" and 60" parts manual.
Pump PN533144 replaced by PN533153.

Details: In a continuing effort to improve product, we have changed to a new pump model. Please insert page "H-1" into its respective place in your "X-treme" parts manuals. Please contact dealers and various customers whom this may affect.