

SERVICE BULLETIN

Date: 8/14/1995

Number: SB9508-14

Subject: Service Bulletin 9507-26 concerning water/antifreeze mixture

Details:

Water level should be checked daily. When doing this, you should also pull radiator screen to check for debris between radiator and screen. If using a pressure washer to remove debris from the radiator, avoid direct contact with cooling fins on the radiator as it may cause damage to the fins.

Thank you, Encore Service Department