



SERVICE BULLETIN


Date:

Number: SB9608-06

Subject: 52" Walk-Behind mower Grass Catcher, part # 151001

Details: The backplate that mounts to the machine must have additional holes drilled into it so the discharge opening will line up. Refer to drawing below for location of new additional holes.

Diagram of Walk-Behind Grass Catcher Backplate



Thank you,
Encore Service Department